

**Table 1 Measured Noise Levels & Observations – Eastwood Brickworks – 29 August 2008**

<b>Measurement Location</b>	<b>Start Time</b>	<b>L<sub>A10</sub> Due to Fill/Stabilisation (dBA)</b>	<b>Noise Limit L<sub>A10</sub> (dBA)</b>	<b>Comments</b>
3 Cobac Avenue	10.50am	44	51	Land fill operations including movements of compactor, roller and excavator constantly just audible at 43-44dBA.
72 Midson Road	8.15am	52	62	Land fill operations including movements of compactor, roller and excavator constantly audible at 51-53dBA.
62 Midson Road	8.30am	53	61	Land fill operations including movements of compactor, roller and excavator constantly audible at 52-54dBA.
45 Midson Road	8.50am	Inaudible	58	Aural inspection at monitoring location indicated land fill operations were inaudible during time of survey.
96a Mobbs Lane	11.50am	61	59	Land fill operations including movements of compactor, roller and excavator was constantly audible (dominant noise sources) at 60-61dBA.
52 Mobbs Lane	9.10am	59	64	Land fill operations including movements of compactor, roller and excavator was constantly audible (dominant noise sources) at 58-59dBA.
15 Skenes Avenue	10.30am	Inaudible	57	Aural inspection at monitoring location indicated land fill operations were inaudible during time of survey.
44 Valley Road	9.30am	Inaudible	60	Aural inspection at monitoring location indicated land fill operations were inaudible during time of survey.
30 Valley Road	9.45am	Inaudible	59	Aural inspection at monitoring location indicated land fill operations were inaudible during time of survey.
Channel 7 (Office façade closest to Mobbs Lane)	11.30am	49	53	Land fill operations including movements of compactor, roller and excavator was constantly audible (dominant noise sources) at 48-50dBA.